

Well it was like that last year mate! and you passed it then!

From 20 May 2018 new fail items are included in the MOT test, NO MATTER HOW LONG YOU HAVE HAD THESE FAULTS they are now FAIL items and will need repair.

BRAKES

ABS warning device MIL indicates a malfunction	major
EBS warning device MIL indicates a malfunction	major
Electronic parking brake MIL indicates a malfunction	major
Brake pad or lining wear indicator illuminated	major
Brake fluid warning light illuminated or defective	minor
Incorrect functioning of brake fluid level warning device	minor

STEERING

EPS MIL indicating a system malfunction	major
---	-------

TYRES

TPMS lamp indicates a system malfunction	minor
--	-------

BODY & STRUCTURE

A tow bar coupling indicator not working	major
--	-------

OTHER EQUIPMENT

An SRS MIL indicates a system malfunction	major
ESC MIL indicates a system malfunction	major
Engine MIL inoperative or indicating a malfunction	major

In case you have forgotten or just been overwhelmed with the endless abbreviations here are the wider descriptions.

ABS - anti-lock braking system
ESC - electronic stability control
MIL - malfunction indicator lamp
TPMS - tyre pressure monitoring system

EBS - electronic braking system
EPS - electronic power steering
SRS - safety restraint system

This information has been brought to you by:-



MOT JUICE
THE UK'S NO1 DVSA COMPLIANCE SUITE

Aftermarket